Oil Field Environmental Incident Summary

Date/Time of Notice: 09/15/2014 07:16 Incident: 20140915071616 Responsible Party: XTO ENERGY INC. Well Operator: XTO ENERGY INC. Well Name: NORMARK 24X-31 Field Name: MCGREGOR Well File #: 19484 Date Incident: 9/14/2014 Time Incident: 22:30 Facility ID Number: **WILLIAMS** Twp: 158 **Rna**: 95 Sec: 31 Qtr: County: Location Description: Submitted By: Kaylan Dirkx Received By: Contact Person: Kaylan Dirkx P.O Box 1589 Sidney, MT 59270 General Land Use: Well/Facility Site Affected Medium: Well/Facility Soil **Distance Nearest Occupied Building:** Distance Nearest Water Well: Type of Incident: Tank Overflow Release Contained in Dike: Yes - Within Dike Reported to NRC: No Spilled Units Recovered Units Followup **Units** 3 Barrels Oil **Brine** Other **Description of Other Released Contaminant:** Inspected: Written Report Received: 10/19/2015 Clean Up Concluded: 9/21/2014 Risk Evaluation: None-spill was contained inside the berm.

Tuesday, January 31, 2017

Areal Extent:

Potential Environmental Impacts:

None-spill was contained inside the berm.

Action Taken or Planned:

The spill was contained within the berm and a cleanup crew has been dispatched. Another tank was open for production.

Wastes Disposal Location: Indian Hills Disposal

Agencies Involved:

Updates

Date: 9/15/2014 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a tank overflow, remained on location within the diking according to the report. NDIC retains oversight.